I.

General Information

0

STATE OF UTAH

DEPARTMENT OF NATURAL RESOURCES DIVISION OF OIL, GAS AND MINING

1594 West North Temple Suite 1210 PO Box 145801 Salt Lake City, Utah 84114-5801

Telephone: (801) 538-5291 Fax: (801) 359-3940



ANNUAL REPORT OF MINING OPERATIONS

The informational requirements of this form are based on provisions of the Mined Land Reclamation Act, Title 40-8, Utah Code Annotated 1953, as amended, and the General Rules as promulgated under the Utah Minerals Regulatory Program. An operator conducting mining operations under a Notice of Intention must file an annual operations and progress report (FORM MR-AR) with the Division.

	1.	Report Time Period: From (mo./yr.) 1/96 To (mo./yr.) 12/96							
	2.	DOGM File Number (Mine No): M/045/037							
	3.	Mine Name: Morton Salt / Grantsville							
	4.	Mineral(s) Mined (or permitted to mine):Salt (Sodium Chloride)							
	5.	Type of mine ☐ Underground Mine							
	6.	Legal Description (Location of Lands Affected):							
		1/4,1/4, Section, Township, Range							
		1/4,1/4, Section, Township, Range							
		1/4,1/4, Section, Township, Range							
	7.	Name of Operator or Company: Morton International, Inc. Morton S	alt	Div					
	8.	Permanent Street Address: I-80 West, Exit 84 (P.O. Box 506)							
		City, State, Zip: Grantsville, UT 84029							
		Phone: 801-250-6335							
	9.	Company Representative (or designated operator):							
		Name:Gary C. Price							
		Title: Facility Manager							
		Business Address: I-80 West, Exit 84 (P.O. Box 506)							
_		City, State, Zip:Grantsville, UT 84029							
		Phone: 801-250-6335							
		☐ Please check if any of the above information has changed since previous year.							
II.	<u>Mining</u>	g and Reclamation							
	1.	Was the mine active during the past year? Yes ☑ No □							
	2.	If active, how much ore or mineral was mined?572,417							

	J. How much additional acre	age was disturbed during the past year?				
	during the past year. This operformed, and volume of r					
	Repair and maintenance	e of existing dykes.				
5.	How much acreage was reclaime	ed during the past year?None				
6.	Briefly describe the reclamation work performed during the past year. This description should include methods employed, and an evaluation of the results.					
7.	What is the total disturbed acreage at years end?15,000					
8.	nd/or reclamation plans for the upcoming year. of the same pond acreage annually.					
NOTE:	Section III., "Additional Informa	tion" applies only to large mining operations.				
I. <u>Additio</u>	onal Information					
1.	An updated surface facilities map should be attached if there have been significant changes since the promap was submitted.					
2.	Any monitoring results or other reports that are required under the terms of the approved notice of in should also be attached.					
V. <u>Signatu</u>	<u>ere Requirement</u>					
I he	ereby certify that the foregoing is t	rue and correct.				
	Name (Typed or Print):	Gary C. Price				
	Title of Operator:	Facility Manager				
•	Signature of Operator:	Say c- Com				
	Date:	2-4-97				
ır-ar						

LOCATION OF OPERATION:

County:	Tooele								
Township:	1N	Range:	5W	Section(s):	19				
Township:	1N	Range:	6W	Section(s):	24, 25, 26, 32, 33, 34, 35				
Township:	1S	Range:	5W	Section(s):	16, 19, 20, 21				
Township:	1S	Range:	7W	Section(s):	1, 2, 3, 10, 11, 12, 13, 14, 15				
Township:	1S	Range:	6W	Section(s):	2, 3, 4, 5, 6, 7, 8, 9, 10, 11,				
					13, 14, 15, 16, 17, 18, 19, 20,				
					21, 22, 23, 24, 25, 26, 27, 28, 29				

